

# Service Report

Requested by: ROV Date: JAN 27, 2024 Warranty:  Non-Warranty:

Company Name: <u>INDUSTRIAL COMPANIES</u>	Customer Service P.O. #:	
Contact Name:	Phone:	Email:
Machine Description: <u>MAYCUT</u>		
Model #: <u>MTC 25-0920</u>	Serial #:	
Date Purchased:	Purchased from:	

Issue: OIL LEAK

Service by:


Service completed: START MACHINE TROUBLE SHOOT OIL LEAK  
REPLACE 'O' RING OF SOLENOID VALVE,  
CORRECT CONNECTIONS, RUN MACHINE,  
TOP UP OIL OF HYD. UNIT

Parts: 1 - PAIL OF HYD. OIL AW32

Service Hours: 5.0 HRS

Travel Hours: 3.0 HRS

Travel Kilometres: 230 km

Customer Signature: 

Customer Name: Steve Danton

Date: JAN 27, 2024