



Service Report

Requested by: Ron Nater
 Company Name: Hathorn Corporation
 Address: 255 Shields Court, Unit C, Markham, Ontario L3R 8V2
 Contact Name: Riley Smith
 Machine Description: vertical machining centre
 Model #: Maxcut MCV-1830
 Date Purchased: 2020-10-19
 Date: 2022-09-20
 Warranty: V Non-Warranty:
 Customer Service P.O. #:
 Phone: 905-604-7040
 Serial #: 1721211852
 Email: riley@hathorncorp.com
 Purchased from: Ron Nater

Issues
 Drive Error 605 cannot be cleared to continue the machine operation.
op motor side feedback cable plug was not all the way in - took 1 min distance not cleaned in

Service by: Fagor service technician Yuli Nikolov
Service completed:
*Open the motor to find it
 Drive - OK
 Drive side cable - OK*

Parts:
Service Hours: *3h*
Travel Hours: *1h*
Travel Kilometres: *80km*

Customer Signature: *[Signature]*
Customer Name: *R. Luck*
Date: *SEPT 22, 2022*